

AM Machinery inspection certificate

Claas Direct Disc 610

#24019-30



Price on request



AMMACHINERY

AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas Direct Disc 610** built in ,with our internal stock number **24019-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-direct-disc-610-24019-30.html>

Technical specifications

Partnumber	24019-30	Brand	Claas
Model	Direct Disc 610	Year of manufacture	2013
Series	Fits claas		


Options

2) Short Description

For sale 2013 Claas Direct Disc 610. This header has been inspected.

3) Product Images





4) Inspection Report

Condition
Header

Brand	Claas	Compression rollers	Yes
Compression rollers bearings	V	Feeder auger fingers	N.A.
Stocknumber	24019	Model	Direct disc 610
Fits for machine serie	494 497 498 502	Working width	6 meter
Header lateral tilt	V	Header height control sensors	N.A.
Header speed gearbox shifting	V	Cutting hours	★ ★ ☆ ☆ ☆
Feeder drums	X*	Cleaners	N.A.
knife discs	X*	Drive shaft	X*
Drive chains and belts	X*	Gearboxes	V
Ground skid plates	V	Hydraulic hoses/lines	V
Transport wagon	X*	Support legs	N.A.
Feeder auger	X*	Feeder auger bearings	V
Side cutting knives condition	N.A.	Wearplates	X*
Canvas	V		

5) Recommended Repairs

Claas 610 DD 3e knife disc LH replacement
 Claas 610 DD chain LH side replacement
 Claas 610 DD Cutting knives replacement
 Claas 610 DD knife disc change LH to RH
 Claas 610 LH driveshaft angled gearbox cover replacement
 Claas 610 RH driveshaft angled gearbox cover replacement
 Claas 610DD center wearplate replacement
 Claas 610DD side wearplates replacement
 Claas dd feederdrums wearstrips replacement
 Transport wagon brake's adjustment
 Welding
 Claas 469 Transport wagon parking brake cable replacement