



Harvester Guard inspection certificate

New Holland 380FP

#24071-30



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **New Holland 380FP** built in ,with our internal stock number **24071-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/new-holland-380fp-24071-30.html>

Technical specifications

Partnumber	24071-30	Brand	New Holland
Model	380 FP	Year of manufacture	2014
Series	FR		

Options

2) Short Description

2014 New Holland 380FP 3.8 meter gras pick up to fit New Holland FR series forage harvesters including, 2 compression rollers and chain lubrication.

3) Product Images





AMMACHINERY



AMMACHINERY



AMMACHINERY



AMMACHINERY

4) Inspection Report

Condition
Header

Stocknumber	24071	Brand	New Holland
Model	380 FP	Automatic chain lubricating	Yes
Hydraulic foldable wheels	Yes	Hydraulic hoses / lines	V
2-speed gearbox	Yes	Compression rollers	X*
Pick-up teeth	X*	Pick-up cam bearings	V
Compression rollers bearings	V	Feeder auger	X*
Feeder auger bearings	V	Feeder auger fingers	X*
Drive chains and sprockets	V	Working width (cm)	380
Oil levels	V		

5) Recommended Repairs

300FP RH bumpstops repl
 300FP theeth 2x stripping plate repl
 380 FPE LH rear wheel axle repl
 380 FPE LH rear wheel repl
 380 FPE RH rear wheelbearing repl
 380FP rear roller replacement
 Automatic chain lubricating pump/tank unit repl
 New Holland 300FPE teeth replacement 10pc
 New Holland 300FPE teeth replacement 10pc
 New Holland 300FPE teeth replacement 10pc
 New Holland 300FPE teeth replacement 10pc
 New holland 300FP/273 LH Pick-up teeth main shaft bearing
 New Holland 300FPE auger paddle replacement
 Pick-up teeth main shaft bearings plastic cover LH repl
 Pick-up teeth maintenance
 Welding 1 hour
 Welding 1 hour
 300FP LH bumpstops repl