Claas Jaguar Double Cut HEMPER

#720210



Price on request





Industriestraat 23 5961 PH Horst The Netherlands T + 31 (0)77 – 2066603 sales@ammachinery.nl https://www.ammachinery.nl/



Dear sir/madame.

Thank you for your interest in our **Claas Jaguar Double Cut HEMPER** built in ,with our internal stock number **720210**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information: **https://www.ammachinery.nl/claas-double-cut-hemper-720210.html**

Technical specifications

Partnumber 720210 Brand Claas

Options

2) Short Description

Hemp harvest equipment - the Double Cut HEMPER®: harvest the hemp CBD flowers and fiber off commercial hemp in one go. Proven hemp harvest equipment method since many years. The Double Cut Hemper is a Claas 830 self-propelled forage harvester, rebuilt and prepared for hemp harvest. It includes a special single knife drum to cut the fiber in pieces off 60 cm (2ft), the Hemper rotary header designed to harvest hemp and prevents congestion and seizing of rotating parts off the tough Hemp crop, a hydraulic lift and last but not least a light weight draper header with left hand belt to harvest the top section of the buds, leaves and flower. Please call us for more information and technical specifications on +31772066603 or visit www.ammachinery.nl

3) Product Images











4) A&M PREMIUM Warranty

All our equipment is inspected with the Harvester-Guard (R) inspection software. This certificate declares that this forage harvester has A&M PREMIUM warranty on:

- 1. All inspected CROP-FLOW components with a 3, 4 or 5 star rating.
- 2. All CROP-FLOW bearings which have status approved.

Warranty on repairs:

Components with 1 or 2 star rating are subject for repair and have no warranty. In case A&M Machinery is ordered to repair the 1 and 2 stars components then warranty is in place, as repair implies upgrade to 5 stars or status approved.

Eventually repairs are reported in the 'A&M PREMIUM or A&M EXCLUSIVE warranty certificate & terms' document.