AM Machinery inspection certificate

New Holland 273FP

#22147-30



Price on request





Industriestraat 23 5961 PH Horst The Netherlands T + 31 (0)77 - 2066603 sales@ammachinery.nl https://www.ammachinery.nl/



Dear sir/madame,

Thank you for your interest in our **New Holland 273FP** built in ,with our internal stock number **22147-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

https://www.ammachinery.nl/new-holland-273fp-22147-30.html

Technical specifications

Partnumber 22147-30 Brand New Holland

Model 273FP Year of manufacture 2008

Options

2) Short Description

For sale 2008 New Holland 273FP 3 meter grass pick up to fit New Holland FR series forage harvesters, including automatic chain lubrication, nice good working pick up which is been inspected and tested.

3) Product Images











4) Inspection Report

Condition Header

| Stocknumber | 22147 | Brand | New Holland |
|-----------------------------|--------|------------------------------|-------------|
| Model | 273 FP | Working width | ☆☆☆☆☆ |
| Automatic chain lubricating | Yes | Hydraulic hoses / lines | X* |
| Compression rollers | V | Pick-up teeth | V |
| Pick-up cam bearings | V | Compression rollers bearings | N.A. |
| Feeder auger | V | Feeder auger bearings | V |
| Feeder auger fingers | X* | Drive chains and sprockets | V |
| Working width | 300 | Oil levels | Χ* |
| | | | |

5)Recommended Repairs

New Holland 300FPE teeth replacement 10pc New Holland 270FP Finger replacement 1 row

New Holland 273FP driveshaft Before C411 replacement

New holland 273FP hoses Automatic chain lubricating repl

New Holland 273FP skidplate wearplate LH replacement

New Holland 273FP skidplate wearplate RH replacement

New holland 300FP/273 LH Pick-up teeth main shaft bearing

New holland 300FP/273 RH Pick-up teeth main shaft bearing

New Holland 300FPE Pump chain lube replacement

New Holland 300FPE suppot leg LH replacement

New Holland 300FPE suppot leg RH replacement