

AM Machinery inspection certificate

# Kemper 460 fits CL

#24021-30



Price on request



**AMMACHINERY**

Industriestraat 23  
5961 PH Horst  
The Netherlands  
T + 31 (0)77 - 2066603  
sales@ammachinery.nl  
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Kemper 460 fits CL** built in ,with our internal stock number **24021-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/kemper-460-fits-cl-24021-30.html>

### Technical specifications

Partnumber	24021-30	Brand	Kemper
Model	460	Year of manufacture	2007
Series	Claas		

### Options

## 2) Short Description

---

2007 Kemper 460 8 row corn header that fits Claas Jaguar forage harvesters. Including Mechanical tilt frame and 2 speed gearbox. This header has been inspected and tested. The inspection report you can find on our website.

## 3) Product Images

---





## 4) Inspection Report

---

Condition  
Header

Stocknumber	24021	Brand	Kemper
Model	460	Amount of rows	8
Working width	6 meter	Autosteer sensor	N.A.
Header lateral tilt	V	Header height control sensors	N.A.
Cutting knives	★☆☆☆☆	Drum bearings	X*
Cleaners	X*	Drums	V
Drum cleaners / scrapers	V	knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	X*	Crop dividers	X*
Oil levels	V	Down corn augers	X*
Ground skid plates	X*	Fold cilinders	V
Hydraulic hoses/lines	X*	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	V
Wearplates	V		

## 5) Recommended Repairs

---

460 3e drum gearbox LH Bottom cover replacement  
 Belt replacement crop divider kemper 460 LH side  
 Belt replacement crop divider kemper 460 RH side  
 Kemper 300/400 down corn auger tensioner bearing replacement LH  
 Kemper 300/400 down corn auger tensioner bearing replacement RH  
 Kemper 400 hose LH control valve to chopper replacement  
 Kemper 400 hose LH control valve to LH cil replacement  
 Kemper 400 hose LH control valve to RH cil replacement  
 Kemper 400 hose RH control valve to RH cil replacement  
 Kemper 460 drum+knife bearing replacement 1e left  
 Kemper 460 drum+knife bearing replacement 3e left  
 Kemper 460 knife and cleaner replacement  
 Kemper 460 plus skid plate 2e left replacement till 127521  
 Kemper 460 plus skid plate 3e left replacement till 127521  
 Welding 2 Hour  
 Welding 2 hour  
 460 2e drum gearbox LH Bottom cover replacement

