

AM Machinery inspection certificate

Kemper 360

#24011-30



Price on request



AMMACHINERY

AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Kemper 360** built in ,with our internal stock number **24011-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/kemper-360-fits-jd-24011-30.html>

Technical specifications

Partnumber	24011-30	Brand	Kemper
Model	360	Year of manufacture	2005
Series	JD 6/7000		

Options

2) Short Description

For sale, 2005 Kemper 360 8 row corn header. Including header lateral tilt. This header has been inspected.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	24011	Brand	Kemper
Model	360	Amount of rows	8
Working width (cm)	6	Autosteer sensor	N.A.
Header lateral tilt	V	Header height control sensors	N.A.
Cutting knives	★ ★ ★ ☆ ☆	Drum bearings	X*
Cleaners	X*	Drums	V
Drum cleaners / scrapers	X*	knife discs	X*
Drive shaft	V	Drive line couplers	X*
Drive chains and belts	X*	Crop dividers	X*
Oil levels	X*	Down corn augers	V
Ground skid plates	X*	Fold cilinders	V
Hydraulic hoses/lines	V	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	V
Wearplates	V		

5) Recommended Repairs

Kemper 300 disc replacement LH 3e disc
 Kemper 300 disc replacement LH 4e disc
 Kemper 300 disc replacement LH 5e disc
 Kemper 300 disc replacement LH 6e disc
 Kemper 300 disc replacement LH 7e disc
 Kemper 300 disc replacement LH 8e disc
 Kemper 300 drum+knife bearing replacement 4e left
 Kemper 300 JD6000/7000 standard main drive gearbox leakage repair
 Kemper 300 skid plate 2e left replacement
 Kemper 300 skid plate 4e left replacement
 Kemper 300 skid plate 5e left replacement
 Kemper 300 skid plate 6e left replacement
 Kemper 300 skid plate 7e left replacement
 Kemper 300 skid plate 8e left replacement
 Kemper 360 2e LH top bow cleaner replacement
 Kemper 360 3e LH top bow cleaner replacement
 Kemper 360 6e LH top bow cleaner replacement

Welding 2 hour

Welding 2 hours

Belt replacement crop divider kemper 300 LH side

Belt replacement crop divider kemper 300 RH side

Cleaners support replacement Kemper 360

Kemper 300 coupler RH side replacement