AM Machinery inspection certificate

Kemper 360 fits CL

#23140-30



Price on request





Industriestraat 23 5961 PH Horst The Netherlands T + 31 (0)77 - 2066603 sales@ammachinery.nl https://www.ammachinery.nl/



Dear sir/madame.

Thank you for your interest in our **Kemper 360 fits CL** built in ,with our internal stock number **23140-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

https://www.ammachinery.nl/kemper-360-fits-cl-23140-30.html

Technical specifications

Partnumber 23140-30 Brand Kemper

Model 360 Year of manufacture 2011

Series Claas

Options

2) Short Description

For Sale, 2011, Kemper 360 8 row corn header. With header lateral tilt. This header has been inspected. The inspection report can be downloaded from our website.

3) Product Images











4) Inspection Report

Condition Header

Stocknumber	23140	Brand	Kemper
Model	360	Amount of rows	8
Working width	6 meter	Autosteer sensor	N.A.
Header lateral tilt	V	Header height control sensors	N.A.
Cutting hours	☆☆☆☆☆	Drum bearings	X*
Cleaners	V	Drums	V
Drum cleaners / scrapers	V	knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	X*	Crop dividers	X*
Oil levels	V	Down corn augers	X*
Ground skid plates	X*	Fold cilinders	٧
Hydraulic hoses/lines	X*	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	X*
Feeder auger	N.A.	Feeder auger bearings	N.A.
Wearplates	X*		

5)Recommended Repairs

Kemper 300 hose's to coupler Claas 492/493

Kemper 300 Lh bolt replacement

Kemper 300 plus RH mainframe outer feedroller drum bearing replacement.

Kemper 300 plus skid plate 1e left replacement

Kemper 300 plus skid plate 3e left replacement

Kemper 300 plus skid plate 8e left replacement

Kemper 300 to Claas angled wearplate feedrolls replacement

Kemper 300/445/4500 down corn auger pully replacement RH

Kemper 300445/4500 down corn auger pully replacement LH

Kemper 360 LH fold cilinder Hoses replacement

Kemper 360 RH fold cilinder Hoses replacement

Welding 2 hours

Belt replacement crop divider kemper 300 LH side