

AM Machinery inspection certificate

New Holland 273

#23127-30



Price on request



AMMACHINERY

AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **New Holland 273** built in ,with our internal stock number **23127-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/new-holland-273-23127-30.html>

Technical specifications

Partnumber	23127-30	Brand	New Holland
Model	273	Year of manufacture	2013

Options

2) Short Description

For Sale, 2013, New Holland 273 grass pickup. This grass pick-up has been inspected. The inspection report can be downloaded from our website.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23127	Brand	New Holland
Model	273	Working width	☆☆☆☆☆
Automatic chain lubricating	Yes	Hydraulic foldable wheels	Yes
Hydraulic hoses / lines	V	Compression rollers	V
Pick-up teeth	V	Pick-up cam bearings	V
Compression rollers bearings	V	Feeder auger	V
Feeder auger bearings	X*	Feeder auger fingers	N.A.
Drive chains and sprockets	X*	Working width	3 meter
Oil levels	X*		

5) Recommended Repairs

New Holland 273 LH chain auger drive replacement
 New Holland 273 LH chain main drive replacement
 New Holland 300FP RH feeder auger bearing replacement
 New holland 300FP/273 LH Pick-up teeth main shaft bearing
 New Holland 300FPE oiltank chain lube replacement before sn538
 New Holland 300FPE teeth replacement 10pc