

AM Machinery inspection certificate

Claas PU300HD

#23116-30



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas PU300HD** built in ,with our internal stock number **23116-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-pu300hd-23116-30.html>

Technical specifications

Partnumber	23116-30	Brand	Claas
Model	PU300HD	Year of manufacture	2007
Series	Claas		

Options

2) Short Description

For sale, 2007, Claas PU300HD grass pick-up. This pickup has been inspected. The inspection report can be downloaded from our website.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23116	Brand	Claas
Model	PU300HD	Working width	☆☆☆☆☆
Hydraulic hoses / lines	V	Compression rollers	V
Pick-up teeth	X*	Pick-up cam bearings	V
Compression rollers bearings	V	Feeder auger	V
Feeder auger bearings	V	Feeder auger fingers	N.A.
Drive chains and sprockets	V	Working width	300
Oil levels	V		

5)Recommended Repairs

Claas pick-up teeth replacement 10pc
 Claas 300 LH lock wheel replacement