

AM Machinery inspection certificate

Claas Orbis 750

#23156-30



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas Orbis 750** built in ,with our internal stock number **23156-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-orbis-750-23156-30.html>

Technical specifications

Partnumber	23156-30	Brand	Claas
Model	Orbis 750	Year of manufacture	2013
Series	659		

Options

2) Short Description

For sale 2013 Claas Orbis 750 10 row corn header. This header has been inspected. The inspection report can be downloaded from our website.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23156	Brand	Claas
Model	Orbis 750	Amount of rows	10
Working width	8 M	Autosteer sensor	N.A.
Header lateral tilt	X*	Header height control sensors	V
Cutting hours	★★★★☆☆	Drum bearings	X*
Cleaners	X*	Drums	V
Drum cleaners / scrapers	X*	knife discs	V
Drive shaft	V	Drive line couplers	V
Crop dividers	X*	Oil levels	V
Down corn augers	X*	Ground skid plates	V
Fold cilinders	V	Hydraulic hoses/lines	V
Transport accident prevention	N.A.	Support wheel(s)	N.A.
Support legs	X*	Wearplates	V

5)Recommended Repairs

Claas Orbis down corn auger bottom bearing RH replacement
 Cleaner replacement knife disc's Orbis 750 (I52,659)
 Orbis 750 659 auto contour cilinder seals replacement
 Orbis 750 659 big drum bearings reeplacement 3e LH
 Orbis 750(i50/659) RH outhter gearbox small disc vertical bearings replacement
 Welding 4 hours
 Welding 4 hours
 Claas orbis 600/750(659) support legs lock RH replacement