

AM Machinery inspection certificate

# Kemper 345

#21185-30



Price on request



**AMMACHINERY**

**AMMACHINERY**

Industriestraat 23  
5961 PH Horst  
The Netherlands  
T + 31 (0)77 - 2066603  
sales@ammachinery.nl  
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Kemper 345** built in ,with our internal stock number **21185-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/kemper-345-fits-jd-21185-30.html>

### Technical specifications

Partnumber	21185-30	Brand	Kemper
Model	345 fits JD	Year of manufacture	2009
Series	JD		

### Options

## 2) Short Description

---

2009 Kemper 345 Corn Header, fits John Deere. 6 rows, 4.5 meter working width. With header lateral tilt. This header has been tested and inspected. The inspection report can be downloaded from our website. For more information please send us a message.

## 3) Product Images

---





## 4) Inspection Report

---

Condition  
Header

Stocknumber	21185	Brand	Kemper
Model	345	Amount of rows	6
Working width (cm)	450	Autosteer sensor	N.A.
Header lateral tilt	V	Header height control sensors	N.A.
Header speed gearbox shifting	V	Cutting knives	★★★★☆
Drum bearings	X*	Cleaners	V
Drums	V	Drum cleaners / scrapers	V
knife discs	V	Drive shaft	V
Drive line couplers	V	Drive chains and belts	X*
Crop dividers	V	Oil levels	X*
Down corn augers	V	Ground skid plates	V
Fold cilinders	V	Hydraulic hoses/lines	V
Transport accident prevention	N.A.	Support wheel(s)	N.A.
Support legs	V	Feeder auger	N.A.
Feeder auger bearings	N.A.	Wearplates	V
Brand	Kemper		

## 5)Recommended Repairs

---

Belt replacement crop divider kemper 300 RH side  
 Drum and knife disc bearing replacement Kemper 300 3e left  
 Kemper 300 drum+knife bearing replacement 3e left  
 Kemper 300 main gearbox LH seal replacement clutchside  
 Kemper 300/400 1e gearbox knifedisc oil leakage top and rear repair  
 Kemper 300/400 2e gearbox knifedisc oil leakage top and rear repair  
 Kemper 300/400 3e gearbox knifedisc oil leakage top and rear repair  
 Kemper 300/400 4e gearbox knifedisc oil leakage top and rear repair  
 Kemper 300/400 5e gearbox knifedisc oil leakage top and rear repair  
 Kemper 300/400 6e gearbox knifedisc oil leakage top and rear repair  
 Belt replacement crop divider kemper 300 LH side