




Kemper 345

#21185-30





Industriestraat 23 5961 PH Horst The Netherlands T + 31 (0)77 – 2066603 sales@ammachinery.nl https://www.ammachinery.nl/



Dear sir/madame.

Thank you for your interest in our **Kemper 345** built in ,with our internal stock number **21185-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

https://www.ammachinery.nl/kemper-345-fits-jd-21185-30.html

Technical specifications

Partnumber 21185-30 Brand Kemper

Model 345 fits JD Year of manufacture 2009


Series JD

Options

2) Short Description

2009 Kemper 345 Corn Header, fits John Deere. 6 rows, 4.5 meter working width. With header lateral tilt. This header has been tested and inspected. The inspection report can be downloaded from our website. For more information please send us a message.

3) Product Images











4) Inspection Report

Condition Header

Stocknumber	21185	Brand	Kemper
Model	345	Amount of rows	6
Working width (cm)	450	Autosteer sensor	N.A.
Header lateral tilt	V	Header height control sensors	N.A.
Header speed gearbox shifting	V	Cutting knives	☆☆☆☆☆
Drum bearings	X*	Cleaners	V
Drums	V	Drum cleaners / scrapers	V
knife discs	V	Drive shaft	V
Drive line couplers	V	Drive chains and belts	X*
Crop dividers	V	Oil levels	X*
Down corn augers	V	Ground skid plates	V
Fold cilinders	V	Hydraulic hoses/lines	V
Transport accident prevention	N.A.	Support wheel(s)	N.A.
Support legs	V	Feeder auger	N.A.
Feeder auger bearings	N.A.	Wearplates	V
Brand	Kemper		

5)Recommended Repairs

Belt replacement crop divider kemper 300 RH side

Drum and knife disc bearing replacement Kemper 300 3e left

Kemper 300 drum+knife bearing replacement 3e left

Kemper 300 main gearbox LH seal replacement clutchside

Kemper 300/400 1e gearbox knifedisc oil leakage top and rear repair

Kemper 300/400 2e gearbox knifedisc oil leakage top and rear repair

Kemper 300/400 3e gearbox knifedisc oil leakage top and rear repair

Kemper 300/400 4e gearbox knifedisc oil leakage top and rear repair

Kemper 300/400 5e gearbox knifedisc oil leakage top and rear repair

Kemper 300/400 6e gearbox knifedisc oil leakage top and rear repair

Belt replacement crop divider kemper 300 LH side