

AM Machinery inspection certificate

Claas PU300HD

#24059-30



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas PU300HD** built in ,with our internal stock number **24059-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-pu300hd-24059-30.html>

Technical specifications

Partnumber	24059-30	Brand	Claas
Model	PU300HD	Year of manufacture	2012
Series	428		


Options

2) Short Description

2012 Claas PU300HD grass pick up, including hydraulic foldable wheels. Nice good working pick-up which is been inspected and tested.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	24059	Brand	Claas
Model	PU 300 HD	Working width	★★★★☆☆
Hydraulic foldable wheels	Yes	Hydraulic hoses / lines	V
Compression rollers	V	Pick-up teeth	X*
Pick-up cam bearings	V	Compression rollers bearings	X*
Feeder auger	V	Feeder auger bearings	X*
Feeder auger fingers	X*	Drive chains and sprockets	X*
Working width	3 M	Oil levels	V

5) Recommended Repairs

Chain adjustment

Claas 300 Front compression roller LH bearing replacement

Claas 300 Front compression roller RH bearing replacement

Claas 300 wheels dump stop replacement LH

Claas 300 wheels dump stop replacement RH

Claas HD300Pro compression roller support bushing replacement

Claas pick-up teeth replacement 10pc

Claas pu300HD adjustable Support leg RH replacement

Claas pu300HD Feeding auger bearings replacement LH

Claas PU300PRO top safety frame gas spring replacement

Feeding auger paddles

LH Wheel fold cilinder seals replacement

Welding 1 Hour

428 Middel support shaft bushings replacement