

AM Machinery inspection certificate

Claas PU300HD

#23178-30



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas PU300HD** built in ,with our internal stock number **23178-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-pu300hd-23178-30.html>

Technical specifications

Partnumber	23178-30	Brand	Claas
Model	PU300HD	Year of manufacture	2010
Series	905		

Options

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23178	Brand	Claas
Model	PU300HD	Hydraulic foldable wheels	Yes
Hydraulic hoses / lines	X*	Compression rollers	X*
Pick-up teeth	X*	Pick-up cam bearings	V
Compression rollers bearings	X*	Feeder auger	V
Feeder auger bearings	V	Feeder auger fingers	V
Drive chains and sprockets	V	Working width	3m
Oil levels	V		

5)Recommended Repairs

Claas 300 Front compression roller RH bearing replacement

Claas pick-up teeth replacement 10pc

Claas pu 300 Hoses to LH wheelcylinder replacement

Claas pu 300 Hoses to lift cylinders auger replacement

Claas pu 300 Hoses to RH wheelcylinder replacement

Welding

Claas 300 Front compression roller LH bearing replacement