AM Machinery inspection certificate

Kemper 345 Plus

#23166-30



Price on request





Industriestraat 23 5961 PH Horst The Netherlands T + 31 (0)77 - 2066603 sales@ammachinery.nl https://www.ammachinery.nl/



Dear sir/madame.

Thank you for your interest in our **Kemper 345 Plus** built in ,with our internal stock number **23166-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

https://www.ammachinery.nl/kemper-345-plus.html

Technical specifications

Partnumber 23166-30 Brand Kemper

Model 345 Plus Year of manufacture 2014

Series Claas

Options

2) Short Description

For sale 2014 Kemper 345 Plus 6 row corn header to fit on Claas Jaguar forage harvesters, nice good working corn header which is been inspected and tested. The inspection report you can find on our website.

3) Product Images











4) Inspection Report

Condition Header

Stocknumber	23166	Brand	Kemper
Model	345 Plus	Amount of rows	6
Working width	4,5 M	Autosteer sensor	N.A.
Header lateral tilt	N.A.	Header height control sensors	N.A.
Cutting hours	☆☆☆☆☆	Drum bearings	٧
Cleaners	X*	Drums	٧
Drum cleaners / scrapers	V	knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	N.A.	Crop dividers	Χ*
Oil levels	V	Down corn augers	N.A.
Ground skid plates	V	Fold cilinders	V
Hydraulic hoses/lines	V	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	٧
Wearplates	V		

5)Recommended Repairs

Welding 3 hours

Cleaners replacement Kemper 345 (plus)